



Intertek Testing Services

ETL Testing Laboratories

Report No.: 9810531

Tested By: Hong, Report No.: 9810531


Scan Settings (1 Range)

Frequencies				Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
450k	30M	5k	10k	PK	20ms	AUTO LN OFF	60dB

Final Measurement: N QP

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Meas Time: 1 s
 Subranges: 16
 Acc Margin: 20dB



Ctrl. No.: N/A

FCC ID: EHK615R



Intertek Testing Services

ETL Testing Laboratories

Report No.: 9810531

Tested By: Hong, Report No.: 9810531

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A

FCC ID: EHK615R