


Tested By: Hong, Report No.: 9810707

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	LF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement:	Transducer No.	Start	Stop	Name
:: OP	3	9k	30M	EI078

Meas Time: 1 s  
 Subranges: 18  
 Acc Margin: 20dB



Ctrl. No.: N/A

FCC ID: EHK615T

# ITS Intertek Testing Services

ETL Testing Laboratories

Report No.: 9810707

Tested By: Hong, Report No.: 9810707

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
16.62000	44.9	48.0

\* limit exceeded

Ctrl. No.: N/A

FCC ID: BHK615T