

Mitel Networks

4000 Innovation Drive, Ottawa, K2K 3K1, Canada

TEL: 613-691-3772

FAX: 613 592-4784

DFS client device channel plan and software operational declaration

Date: 2022-06-17

We, **Mitel Networks**, declare that the device, FCC ID: **EHTPERS1** Model Name: **6920w**, does not have Ad Hoc on “non-US frequencies” and/or on “DFS frequencies”. Also, the client software and associated drivers will not initiate any transmission on DFS frequencies without initiation by a master. This includes restriction on transmissions for beacons and support for ad-hoc peer-to-peer modes.

Below is the channel / frequency plan for the device

CH	1	2	3	4	5	6	7	8	9	10	11
Frequency (MHz)	2412	2417	2422	2427	2432	2437	2442	2447	2452	2457	2462
Scan Type	Active	Active	Active	Active	Active	Active	Active	Active	Active	Active	Active

5G band 1

CH	36	40	44	48						
Frequency (MHz)	5180	5200	5220	5240						
Scan Type	Active	Active	Active	Active						

5G band 2

CH	52	56	60	64						
Frequency (MHz)	5260	5280	5300	5320						
Scan Type	Passive	Passive	Passive	Passive						

5G band 3

CH	100	104	108	112	116	120	124	128	132
Frequency (MHz)	5500	5520	5540	5560	5580	5600	5620	5640	5660
Scan Type	Passive	Passive	Passive	Passive	Passive	Passive	Passive	Passive	Passive
CH	136	140							
Frequency (MHz)	5680	5700							
Scan Type	Passive	Passive							

5G band 4

CH	149	153	157	161	165		
Frequency (MHz)	5745	5765	5785	5805	5825		
Scan Type	Active	Active	Active	Active	Active		

Also, on DFS channels, the WLAN driver in the device operates under the control of an AP at all times, except when in ad-hoc mode on US non-DFS channels. The device passively scans DFS frequencies until a master device is detected. The control of this functionality is not accessible to anyone under any conditions. Furthermore, the firmware is protected by a special signature and CRC checksum. Signature and CRC checksum will be calculated and verified before firmware upgrade. Unauthorized modification to firmware will lead to the failure of verification and thus firmware upgrade will not be allowed.

Sincerely yours,

Mitel Networks

4000 Innovation Drive, Ottawa, K2K 3K1, Canada

TEL: 613-691-3772

FAX: 613 592-4784



Paul Scott, Senior Manager, Regulatory Approvals

Mitel Networks

TEL: 613-691-3772

FAX: 613 592-4784

Email: paul.scott@mitel.com