


EMC Technologies Report Number: M050508_Cert_WLL4070_11abg_NII_BT

APPENDIX K
Harmonics - WLL4070 802.11a (NII)



Harmonics – Channel 36

Marker 1 [T1]	RBW	300 kHz	RF Att	30 dB
Ref Lvl	2.05 dBm	VBW	1 MHz	
15 dBm	5.14228457 GHz	SWT	1.1 s	Unit dBm




Date: 9.JUN.2005 10:46:52



Harmonics - Channel 42

	Marker 1 [T1]	RBW	300 kHz	RF Att	30 dB
Ref Lvl	0.07 dBm	VBW	1 MHz		
15 dBm	5.22044088 GHz	SWT	1.1 s	Unit	dBm




Date: 9.JUN.2005 10:50:54



Harmonics - Channel 50

Ref Lvl	0.35 dBm	RBW	300 kHz	RF Att	30 dB
15 dBm	5.22044088 GHz	VBW	1 MHz	Unit	dBm
		SWT	1.1 s		




Date: 9.JUN.2005 10:54:04



Harmonics - Channel 52

Ref Lvl	6.02 dBm	RBW	300 kHz	RF Att	30 dB
15 dBm	5.22044088 GHz	VBW	1 MHz	Unit	dBm
		SWT	1.1 s		




Date: 9.JUN.2005 10:38:31



Harmonics - Channel 58

Marker 1 [T1]	RBW	300 kHz	RF Att	30 dB
Ref Lvl	4.26 dBm	VBW	1 MHz	
15 dBm	5.22044088 GHz	SWT	1.1 s	Unit dBm




Date: 9.JUN.2005 10:56:22



Harmonics - Channel 64

Marker 1 [T1]	RBW	300 kHz	RF Att	30 dB
Ref Lvl	5.66 dBm	VBW	1 MHz	
15 dBm	5.29859719 GHz	SWT	1.1 s	Unit dBm



Date: 9.JUN.2005 10:43:02

