


EMC Technologies Report Number: M050532_Cert_WLL4070_11abg_DTS_BT

APPENDIX K1
Harmonics - Atheros 802.11a



Harmonics – Channel 149

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl -2.17 dBm VBW 300 kHz
15 dBm 5.68937876 GHz SWT 9.8 s Unit dBm




Date: 5.JUN.2005 14:59:35



Harmonics - Channel 157

Marker 1 [T1]	RBW	100 kHz	RF Att	30 dB
Ref Lvl	-2.30 dBm	VBW	300 kHz	
15 dBm	5.76753507 GHz	SWT	9.8 s	Unit dBm




Date: 5.JUN.2005 14:54:29



Harmonics - Channel 165

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl -0.95 dBm VBW 300 kHz
15 dBm 5.76753507 GHz SWT 9.8 s Unit dBm




Date: 5.JUN.2005 14:45:45



Harmonics - Channel 152 (Turbo)

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl -1.89 dBm VBW 300 kHz
15 dBm 5.76753507 GHz SWT 9.8 s Unit dBm




Date: 5.JUN.2005 15:02:33



Harmonics - Channel 160 (Turbo)

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl -1.52 dBm VBW 300 kHz
15 dBm 5.76753507 GHz SWT 9.8 s Unit dBm



Date: 5.JUN.2005 15:10:59

