


**EMC Technologies Report Number: M050750\_Cert\_WLL4070\_DTS\_BT**

**APPENDIX K1  
Harmonics - Atheros 802.11a**



**Harmonics – Channel 149**

	Marker 2 [T1]	RBW	100 kHz	RF Att	30 dB
Ref Lvl	-44.18 dBm	VBW	300 kHz		
15 dBm	3.83166333 GHz	SWT	9.8 s	Unit	dBm




Date: 16.AUG.2005 16:22:39



### Harmonics - Channel 157

Ref Lvl	Marker 2 [T1]	RBW	100 kHz	RF Att	30 dB
15 dBm	-43.72 dBm	VBW	300 kHz		
	3.83166333 GHz	SWT	9.8 s	Unit	dBm




Date: 16.AUG.2005 16:20:23



Harmonics - Channel 165

Marker 2 [T1] RBW 100 kHz RF Att 30 dB  
Ref Lvl -42.36 dBm VBW 300 kHz  
15 dBm 3.83166333 GHz SWT 9.8 s Unit dBm




Date: 16.AUG.2005 16:17:21



### Harmonics - Channel 152 (Turbo)


Marker 2 [T1] RBW 100 kHz RF Att 30 dB  
Ref Lvl -42.21 dBm VBW 300 kHz  
15 dBm 3.83166333 GHz SWT 9.8 s Unit dBm



Date: 16.AUG.2005 16:10:55

### Harmonics - Channel 160 (Turbo)





Date: 16.AUG.2005 16:14:37

