



EMC Technologies Pty Ltd
ABN 82 057 105 549
57 Assembly Drive
Tullamarine Victoria Australia 3043

Ph: + 613 9335 3333
Fax: + 613 9338 9260
email: chris@emctech.com.au

To:	Federal Communications Commission
Attention:	Stanley Lyles
No of Pages:	1
Subject:	FCC ID: EJE-WB0035

FCC Query: External photos shows L, R antennas; SAR report has A, B antenna ports – what is correspondence?

1. The external photos exhibits shows antenna – L & R.

The Left antenna connects to Auxiliary antenna port (as marked on WLAN). The SAR test report has therefore been updated to show that antenna 'B' is actually the Auxiliary antenna.

The Right antenna connects to Main antenna port (as marked on WLAN). The SAR test report has therefore been updated to show that antenna 'A' is actually the Main antenna.

Updated SAR test reports M050753_Cert_WM3B2915ABG_SAR_2.4 & M050753_Cert_WM3B2915ABG_SAR_5.2 have been uploaded today as exhibits – RF Exposure Information.