

From: hliana@ccsemc.com.tw
Sent: Thursday, January 15, 2004 8:24 PM
To: scheng@ccsemc.com
Cc: cert@ccsemc.com.tw
Subject: RE: AN04T3592 NUTEK ALARM ELVNTRCB

Hi Steve,
Please find attached e-mail by Naomi below.

If you have any further comments, please feel free to contact us.

Best regards,

Liana Hsiung (熊連枝)

=====

程智科技股份有限公司
Compliance Certification Services Inc. (Hsintien Lab.)
No.165, Chunghsen Road, Hsintien City, Taipei Hsien, Taiwan
TEL:+886-2-2217-0894*10
FAX:+886-2-2217-1029
hliana@ccsemc.com.tw
=====

----- 轉呈者 hliana/ccsemc 於 2004/01/16 12:01 PM -----
znaomi
張家菁
2004/01/16 11:35 AM

收件人： hliana/ccsemc@ccsemc
副本抄送：
主旨： RE: AN04T3592 NUTEK ALARM
ELVNTRCB連結

TCB Review Questions for AN04T3592 NUTEK ALARM ELVNTRCB

Question #1: Schematic is not readable, please submit a new copy.
--->Attached please find Schematic.jpg.

Question #2: Users manual does not have the info according to "CFR47
Section 15.21". Please revise users manual to include the info.
--->Attached please find new users manual.

Question #3: Users manual is very blurry; please resubmit a clear copy if
possible.
--->Sorry about that! because the customer didnt provide us the file,
just paper only. if there is any question, please don't hesitate to
contact me.

Question #4: Test report Page 5, ESVS30 and R3132 are out of cal. Please
explain why those equipments were used on the test.
--->The date tested in July 07, 2003 and July 10, 2003. so ESVS30 and
R3132 aren't out of cal. or maybe u have any suggestion in the question.

Although u didnt ask the Question #5 in this e-mail, but u ask the question in the "AN04T3593 NUTEK ALARM ELVNTRCA" e-mail, so i update it here.

Question #5: Test report page 10, 15.205 is marked as not necessary. Please explain why 15.205 do not apply?
--->Sorry about that! Attached please find C30710401-RP (NUTEK ELVNTRCB).pdf.

Best Regards

Naomi Zhang

TCB Review Questions for AN04T3592 NUTEK ALARM ELVNTRCB

-EMC-

Question #1: Schematic is not readable, please submit a new copy.

Question #2: Users manual does not have the info according to "CFR47 Section 15.21". Please revise users manual to include the info.

Question #3: Users manual is very blurry; please resubmit a clear copy if possible.

Question #4: Test report Page 5, ESVS30 and R3132 are out of cal. Please explain why those equipments were used on the test.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best Regards

Steve Cheng / TCB Technical Reviewer
Compliance Certification Services
561F Monterey Road
Morgan Hill, CA 95037
Tel:(408) 463-0885 x: 119
Fax:(408) 463-0888
scheng@ccsemc.com
<http://www.ccsemc.com>