



2111 North Molter Road Liberty Lake, Washington 99019 509.924.9900 Tel 509.891.3355 Fax 800.635.5461 www.itron.com

24 April 2020

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

Subject: Tune Up Information

FCC ID: E09DCU5310C

Dear Sir/Madam:

There is no tune-up procedure for this device. The frequency and amplitude of the transmitter cannot be changed by the end user. Routine calibration is performed whenever the device is returned for service.

Sincerely,

Jay R. Holcomb

Jag R. Holemb

R&D Spectrum Regulatory jay.holcomb@itron.com

Itron, Inc.

Enclosure: other exhibits

cc: n/a