



2111 North Molter Road Liberty Lake, Washington 99019 509.924.9900 Tel 509.891.3355 Fax 800.635.5461 www.itron.com

## **Technical Description – the handheld super raptor radio (HHSR)**

Date: 02/28/2007

To: CKC Certification Services

Applicant: Itron, Inc. FCC ID: EO9HHSRISM

Dear Examiner,

The following requirements will be applied to any products that use this module:

1) The label will include the following text:

Contains FCC ID: EO9HHSRISM IC: 864A-HHSRISM

The user's manual for any product that contains this module will contain the following text. If the device is large enough, then this will also be placed on the label.

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation."

3) The user's manual for any product that contains this module will contain the following text:

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- -- Reorient or relocate the receiving antenna.
- -- Increase the separation between the equipment and receiver.
- -- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- -- Consult the dealer or an experienced radio/TV technician for help.





2111 North Molter Road Liberty Lake, Washington 99019 509.924.9900 Tel 509.891.3355 Fax 800.635.5461 www.itron.com

4) The user's manual for any product that contains this module will contain the following text:



## **Modification and Repairs**

To ensure FCC compliance and system performance, this device, antenna and/or coaxial assembly shall not be changed or modified without the express written approval of Itron. Any unauthorized modification will void the user's authority to operate the equipment. **WARNING!** This device contains no user serviceable parts. Attempts to repair this device by unauthorized personnel may subject the person to shock hazard if removal of protective covers is attempted. Unauthorized repair will void the warranty and/or maintenance contract with your company.

Regards,

Drew Rosenberg Engineering Project Manager 509-891-3481 Drew.rosenberg@itron.com