

<p>Test report 99119-7 on page 19 indicates frequency range of investigation to be from 9kHz to 9.28GHz. however equipment operational frequency is 952MHz. The frequency range of investigation does not encompass the range required by 15.33, to the 10<sup>th</sup> harmonic. Please clarify equipment compliance.</p>	<p>Test lab confirmed the frequency range investigated extended to 10GHz, the report includes a typo left over from ISM testing.</p>	<p>MA 12/12/16</p>
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------	--------------------