

DATE : May 25, 2010

Equipment Autorisation Division
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

FCC ID: EOTBDP4-EXCT438
Product Name: SDR-T-001-438 Exciter

Tune Procedure

There is no end user tune up procedure. The equipment is tuned at the factory before shipment. Each SDR-T-001-438 exciter goes through an automatic tune station to be calibrated in power, modulation deviation and frequency error. Tune information for the exciter is stored in non-volatile memory and a record is kept by the manufacturer.

If during an annual maintenance check, the exciter's calibration is found to be off, we recommend to the end user to come into contact with our field support group and initiate an RMA request.

Dated this 25 **Day of** May 20 10

By: Richard Vallée **Richard Vallée**
Signature **Printed**

Title: Senior Hardware Engineer

On behalf of : CalAmp Corp.

Telephone: 514-737-0020 x238