

Date: June 23, 2008


To: FCC

From: Larry Canady, [larry.canady@bsci.com](mailto:larry.canady@bsci.com)  
Guidant Corporation  
4100 Hamline Ave. N.  
Arden Hills, MN 55112


Subject: Internal Photos – Application for Equipment Certification, FCC ID:  
ESCCRM647608

The following are internal photos of the Guidant Corporation (a wholly owned subsidiary of Boston Scientific Corporation doing business as Boston Scientific Cardiac Rhythm Management) Model 6476 LATITUDE™ Communicator transceiver circuitry.


**Figure 1. Main Circuit Board – Top View**



**Figure 2. Transceiver Section – Top View**



**Figure 3. Main Board – Bottom View**



Bottom of RF  
Transceiver  
Section

Figure 4. Transceiver Section - Bottom View

