

## Request for Class II Permissive Change

FCC ID: ESV-0117-05    FCC ID 号码

Date: 06-Nov-2015

TO: Federal Communication Commission

Please be notified that we, the undersigned, Bosch Security Systems, Inc. declare that the reasons for this Class II permissive change are as below:

New **SE88-90S-304** is added in SE88 family with the following differences.

Software:


This model has same RF transmitter portion and the only difference is the supervisory time of which SE88-90S-304 is 90 seconds.

Enclosure:

New enclosure and battery contacts design for SE88-90S-304. Remove the Alarm button in new enclosure, alarm function is not accessible by users.

Thank you.  
Sincerely.

By:

  
\_\_\_\_\_  
(Signature<sup>1</sup>)

\_\_\_\_\_  
Peter Namisnak  
(Print name)

Title:

\_\_\_ **Regulatory Compliance Coordinator** \_\_\_

On behalf of: \_\_\_ Bosch Security Systems Inc  
(Company Name)

Telephone:    \_\_\_+1 585 678-3462\_