

EXHIBIT 4

Block Diagram and Schematic

Para. 2.1033(b)(5)



**Retlif Testing Laboratories**

Test Report No. R-7478-1  
FCC ID: ESV-0406-1



DETECTION SYSTEMS, INC.

130 PERINTON PARKWAY  
FAIRPORT, NEW YORK 14450 USA

phone: 716-223-4060

FAX: 716-223-9180

### Block Diagram of RF3222 Receiver

