

## Lucy Tsai

---

**From:** elise.tang [elise.tang@cn.ccsemc.com]  
**Sent:** Thursday, March 27, 2008 9:39 PM  
**To:** Lucy Tsai  
**Cc:** 'miro.chueh'; lin.zhang@cn.ccsemc.com  
**Subject:** 答复: First International Computer Inc, FCC ID: EUNGE3A, Assessment NO.: AN08T7758, Notice#1-revised  
**Attachments:** IntPho Rev1.pdf; system schematics.pdf; User manual.pdf; AW-GU701-DS.pdf; AW-GU701\_schematic.pdf

Dear Lucy,

Please see my answer below:

Q#1: As indicated in the user manual and system block diagram, except the WLAN, this mini EPC also has a Bluetooth module inside which doesn't agree with the application. Please submit another application with equipment code of DSS to address Bluetooth portion.

<Elise>The bluetooth module has removed from the mini EPC.  
User manual and system block diagram were updated.

Q#2: The RF exposure statement doesn't address co-location issue for Bluetooth and WLAN modules. Please revise.

<Elise>The bluetooth module has removed from the mini EPC.

Q#3: As indicated in page 13 of internal photos, the module should be a RF transmitter. Is it the Bluetooth module as mentioned in the user manual? Please clarify and submit for another application as well.

<Elise>The bluetooth module has removed from the mini EPC.

Q#4: As indicated in the user manual, the WLAN module equipped is Intel 3945ABG but internal photos shown the WLAN module is AzureWave RTL8187B 802.11bg mini module. Please clarify and do the necessary correction.

<Elise>please check attached corrected user manual.pdf.

Q#5: As indicated in the label format, the FCC DOC procedure is used instead of getting certification. Then, please provide a statement, including the test site and report no. to demonstrate FCC Part 15B DOC test report has been done.

<Elise>Test site:The device was tested by Compliance Certification Services Inc. (Designation Number: TW1026) in No. 81-1, Lane 210, Bade 2nd Rd., Lujhu Township, Taoyuan County, Taiwan.  
Reopr No:KS071214A01

Q#6: Please provide complete WLAN RF module's schematics.

<Elise>please check attached file AW-GU701\_schematic.pdf.

Q#7: Please provide operational description of WLAN portion.

<Elise>please check attached file AW-GU701-DS.pdf.

Have a nice day!

**Best Regards, Elise Tang / 春?**

**Compliance Certification Services (Kunshan) Inc.**

**Tel: 0512-57355888 ext. 256**

**Fax: 0512-57370818**

**E-mail: [elise.tang@cn.ccsemc.com](mailto:elise.tang@cn.ccsemc.com)**

---

? 件人: [miro.chueh \[mailto:miro.chueh@tw.ccsemc.com\]](mailto:miro.chueh@tw.ccsemc.com)

? 送? ? : 2008 年 3 月 28 日 10:06

收件人: [elise.tang@cn.ccsemc.com](mailto:elise.tang@cn.ccsemc.com)

主? : RE: First International Computer Inc, FCC ID: EUNGE3A, Assessment NO.: AN08T7758, Notice#1-revised

Best Regards,

EMC Dept. / EMC 測試部

Miro Chueh / 關濟維

-----  
程智電子科技(昆山)股份有限公司

Compliance Certification Service (Kun Shan) Inc.

江蘇省昆山市(留學創業園)偉業路 10 號

No. 10, Wei-Ye Rd., Innovation park, Eco&Tec, Development Zone, Kun Shan City, Jiang Su,  
P.R.O.C.

Zip code: 215300

Tel: +86-512-5735-5888 ext.218

Fax: +86-512-5737-0818

E-Mail: [miro.chueh@cn.ccsemc.com](mailto:miro.chueh@cn.ccsemc.com)/[miro.chueh@tw.ccsemc.com](mailto:miro.chueh@tw.ccsemc.com)

Mobile: +86-135-1163-1599

----- 轉呈者 [miro.chueh@cn.ccsemc.com](mailto:miro.chueh@cn.ccsemc.com) 於 2008/03/28 10:03 AM -----

"Lucy Tsai"

[lucy.tsai@ccsemc.com](mailto:lucy.tsai@ccsemc.com)

收件人: <[elise.tang@cn.ccsemc.com](mailto:elise.tang@cn.ccsemc.com)>, <[miro.chueh@tw.ccsemc.com](mailto:miro.chueh@tw.ccsemc.com)>

副本抄送:

2008/03/25 01:33 AM

主旨: RE: First International Computer Inc, FCC ID: EUNGE3A, Assessment NO.: AN08T7758, Notice#1-revised

Hi Elise,

One more question is added.

-----Original Message-----

From: Lucy Tsai  
Sent: Monday, March 24, 2008 10:24 AM  
To: 'elise.tang@cn.ccsemc.com'; 'miro.chueh@tw.ccsemc.com'  
Subject: FW: First International Computer Inc, FCC ID: EUNGE3A,  
Assessment NO.: AN08T7758, Notice#1

Hi, Elise,

Please address following issues.

Q#1: As indicated in the user manual and system block diagram, except the WLAN, this mini EPC also has a Bluetooth module inside which doesn't agree with the application. Please submit another application with equipment code of DSS to address Bluetooth portion.

Q#2: The RF exposure statement doesn't address co-location issue for Bluetooth and WLAN modules. Please revise.

Q#3: As indicated in page 13 of internal photos, the module should be a RF transmitter. Is it the Bluetooth module as mentioned in the user manual? Please clarify and submit for another application as well.

Q#4: As indicated in the user manual, the WLAN module equipped is Intel 3945ABG but internal photos shown the WLAN module is AzureWave RTL8187B 802.11bg mini module. Please clarify and do the necessary correction.

Q#5: As indicated in the label format, the FCC DOC procedure is used instead of getting certification. Then, please provide a statement, including the test site and report no. to demonstrate FCC Part 15B DOC test report has been done.

Q#6: Please provide complete WLAN RF module's schematics.

Q#7: Please provide operational description of WLAN portion.

Hi Miro,

Please just help to check if Elise has received this email, thank you.

Best Regards,

Lucy

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.