Report No: KS060803A01

INTERNAL PHOTOGRPHS OF EUT







Report No: KS060803A01





CCS Compliance Certification Services Inc. Report No: KS060803A01



Motherboard



Page 3




Report No: KS060803A01



Page 4 This report shall not be reproduced except in full, without the written approval of Compliance Certification Services.



Report No: KS060803A01



Page 5 This report shall not be reproduced except in full, without the written approval of Compliance Certification Services.





Report No: KS060803A01


RAM







This report shall not be reproduced except in full, without the written approval of Compliance Certification Services.



This report shall not be reproduced except in full, without the written approval of Compliance Certification Services.



Report No: KS060803A01





Page 10 This report shall not be reproduced except in full, without the written approval of Compliance Certification Services.

Report No: KS060803A01

ODD





This report shall not be reproduced except in full, without the written approval of Compliance Certification Services.

Page 11






Report No: KS060803A01

Bluetooth Module











Report No: KS060803A01






This report shall not be reproduced except in full, without the written approval of Compliance Certification Services.

Page 16



Page 17 This report shall not be reproduced except in full, without the written approval of Compliance Certification Services.







Page 18 This report shall not be reproduced except in full, without the written approval of Compliance Certification Services.



Report No: KS060803A01



Page 19 This report shall not be reproduced except in full, without the written approval of Compliance Certification Services.

