

---

**INTERTEK TESTING SERVICE**

Report No.: 16060975HKG-001

**Equipment Photographs**

**Model : VM345 BU**

**(Internal)**



---


# INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

## Equipment Photographs

Model : VM345 BU

(Internal)



---


# INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

## Equipment Photographs

Model : VM345 BU

(Internal)



---

**INTERTEK TESTING SERVICE**

Report No.: 16060975HKG-001

**Equipment Photographs**

**Model : VM345 BU**

**(Internal)**



---

# INTERTEK TESTING SERVICE

---

Report No.: 16060975HKG-001

## Equipment Photographs

Model : VM345 BU

(Internal)



---



# INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

## Equipment Photographs

Model : VM345 BU

(Internal)



---



# INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

## Equipment Photographs

Model : VM345 BU

(Internal)



---


# INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

## Equipment Photographs

Model : VM345 BU

(Internal)





---


# INTERTEK TESTING SERVICE

Report No.: 16060975HKG-001

## Equipment Photographs

Model : VM345 BU

(Internal)



---

# INTERTEK TESTING SERVICE

---

Report No.: 16060975HKG-001

## Equipment Photographs

Model : VM345 BU

(Internal)

