

Response to TCB Findings

1. Please confirm that the harmonics upto 40GHz or upto 10th harmonic of 5.8GHz have been checked during radiated emissions testing.

Yes, we confirm that the harmonics have been checked.

2. The internal pictures of 5850 base shows copper tapes under the shielding can of the RF circuitry. Has this been implemented by VTech? Is this going to be on all final products. Please clarify.

Yes, it will be on all final products until Vtech has a better solution, which is more manufacturable. The copper tape there is the fix to shield a gap between the shield wall and the shield can. See below response from VTECH.

VTECH: The copper tape there is the fix to shield a gap between the shield wall & the shield can. So, the answer is: Yes, it will be on all final products until we have a better solution, which is more manufacturable. For the later solution, we understand that we have to go through either Class I or Class II permissive change process.