

Hi Ruby,

We have identified these issues following our review of the application:

1. In the test report there are two tables labeled spurious harmonics. There is no indication that non-harmonic spurious were checked or that none were found.

Response –Revised test report supplied.

2. The second radiated spurious table does not indicate the detector type.

Response – Revised test report supplied.

3. Modification note on page 4 indicates that testing was not repeated after modification because the client indicated it would have no effect on the test results. What is the laboratory's assessment of this change?

Response – see response from Vtech.

Best regards

Barry C. Quinlan  
Certification Manager  
Curtis-Straus TCB