

To : Federal Communications Commission (FCC)&TCB

Attn. : Reviewing Engineer

Date : 25 Jun 2010

RE. : Filing Revision Notification

Intertek Testing Services FCC/IC Report No. HK10041003-1 dated 24 May 2010.

Please be informed that all the content recorded in the above captioned report will be voided. These captioned report are now superseded by revised Intertek Testing Services report number HK10041003-1(R1) dated 25 Jun 2010.

In Report No. HK10041003-1(R1), the following has been changed:

Pages

5, 10, 13, 19-22, 27-31, 33, 35-37 of 39 of "report.pdf", "conduct.pdf", "config photos.pdf", and "be.pdf".

Description

The correct brand name of tested adaptor should be "SIL". Superseded report only revises the wrong adaptor name "Salcomp" to be "SIL". The test results and others remain unchanged.

Thank you for your attention.



Nip Ming Fung, Melvin
Supervisor