

天祥公證行有限公司

Intertek Testing Services Hong Kong Ltd. 香港九龍青山道五七六號製衣中心二字樓 2/F., Garment Centre, 576 Castle Peak Road Kowloon, Hong Kong.

Telephone (852) 2173 8888 Facsimile (852) 2786 1903 www.intertek.com

To: VTech Telecommunications Ltd. Ref.: TC-SP808

Attn.: Samson Man Date: 02 Sep 2010

RE. : Report Revision Notification

Intertek Testing Services FCC Report No. HK10070763-1 dated 12 Aug 2010.

Please be informed that all the content recorded in the above captioned report will be voided. These captioned report are now superseded by revised Intertek Testing Services report number HK10070763-1(R1) dated 02 Sep 2010.

In Report No. HK10070763-1(R1), the following has been changed:

Pages

Pages 10 of 33 Section 3.1 Justification

Description

Type error, previous granted model changed from CS6124 to CS6114-2.

The last paragraph is revised as below statement "For IC, RF module for base unit of CS6124 is the same with previous granted model CS6114-2. Therefore conducted emission measurement for CS6124 is skipped."

Thank you for your attention.

Nip Ming Fung, Melvin

Supervisor