


# INTERTEK TESTING SERVICES

## Internal photos




Test Report Number: 16070865HKG-001  
FCC ID: EW780-0443-00  
IC: 1135B-80044300

# INTERTEK TESTING SERVICES

---


## Internal photos



Test Report Number: 16070865HKG-001  
FCC ID: EW780-0443-00  
IC: 1135B-80044300

# INTERTEK TESTING SERVICES


## Internal photos



# INTERTEK TESTING SERVICES

---

## Internal photos





Test Report Number: 16070865HKG-001  
FCC ID: EW780-0443-00  
IC: 1135B-80044300

# INTERTEK TESTING SERVICES

---

## Internal photos





Test Report Number: 16070865HKG-001  
FCC ID: EW780-0443-00  
IC: 1135B-80044300

# INTERTEK TESTING SERVICES

---



## Internal photos



Test Report Number: 16070865HKG-001  
FCC ID: EW780-0443-00  
IC: 1135B-80044300

# INTERTEK TESTING SERVICES

## Internal photos





Test Report Number: 16070865HKG-001  
FCC ID: EW780-0443-00  
IC: 1135B-80044300

# INTERTEK TESTING SERVICES

---



## Internal photos



Test Report Number: 16070865HKG-001  
FCC ID: EW780-0443-00  
IC: 1135B-80044300

# INTERTEK TESTING SERVICES

## Internal photos





Test Report Number: 16070865HKG-001  
FCC ID: EW780-0443-00  
IC: 1135B-80044300

## INTERTEK TESTING SERVICES

---

### Internal photos





Test Report Number: 16070865HKG-001  
FCC ID: EW780-0443-00  
IC: 1135B-80044300

# INTERTEK TESTING SERVICES

---

## Internal photos



Test Report Number: 16070865HKG-001  
FCC ID: EW780-0443-00  
IC: 1135B-80044300

# INTERTEK TESTING SERVICES

## Internal photos




Test Report Number: 16070865HKG-001  
FCC ID: EW780-0443-00  
IC: 1135B-80044300

# INTERTEK TESTING SERVICES

---

## Internal photos



Test Report Number: 16070865HKG-001  
FCC ID: EW780-0443-00  
IC: 1135B-80044300