



One Viper Way
Vista, CA 92081-7853

P. 760.598.6200
F. 760.598.6400
www.directed.com

Tuesday, October 04, 2011

Nemko Canada Inc
303 River Road
Ottawa, Ontario, Canada

K1V 1H2

Attn: Director of Certification

IC: 1513A-3807
FCC ID: EZSDEI3807

Models: 3807A, 3808A

The 3808A and 3807A differences:

The 3808A and 3807A have a common schematic, BOM and PCB. The only differences are:

- The software that have different features for car control.

A handwritten signature in black ink, appearing to read "Minas Minassian".

Minas Minassian
RF Engineering Manager