

Mr. Joe Dichoso  
Re: FCC ID: F3JSP150U1; Maxon Telecom Ltd. (USA)  
Correspondence Reference Number: 18580  
731 Confirmation Number EA99737  
FCC Inquiry dated 26 March 2001

Per referenced FCC inquiry:

1. List of component changes:

	SP150U1	SP150U2
C-133	8.1 pf	4.7 pf
C-135	10 pf	9 pf
C-136	1 pf	1.2 pf
C-137	9 pf	8.2 pf
C-138	4.7 pf	4 pf
C-142	8 pf	7 pf
C-151	18 pf	15 pf
L-11	18 nH	15 nH

The following modular components are hand built to frequency range of operation for each lot of active devices with matching component values adjusted according to need on the respective assembly lines, for the band intended. These modules are not meant to be field repairable.

Power Amp Module:

U-1 Maxon Part Number 770-230-0029  
U2 Maxon Part Number 770-230-0018

Front End Module:

U-1 Maxon Part Number 770-230-0025  
U-2 Maxon Part Number 770-230-0018

VCO Module:

U-1 Maxon Part Number 770-230-0038  
U-2 Maxon Part Number 770-030-0027

2. Separate .jpg photos have been uploaded per request.
3. SAR test report has been uploaded via add attachments.