

---

**From:** "Ruby Dulmage" <ruby.dulmage@nemkona.com>  
**To:** "Curtis-Straus Certification Dept." <certification@curtis-straus.com>  
**Sent:** Friday, February 28, 2003 1:56 PM  
**Attach:** 3W06855-2.pdf  
**Subject:** Re: Revised test report - Digital Security Controls FCC ID: F5303RF5108

Hi Barry:

See attached revised test report which also contains the calibration dates for the test equipment.

Thanks and have a good weekend.

Ruby

----- Original Message -----

**From:** [Curtis-Straus Certification Dept.](#)  
**To:** [Ruby Dulmage](#)  
**Sent:** Friday, February 21, 2003 6:00 PM  
**Subject:** Digital Security Controls FCC ID: F5303RF5108

Hi Ruby,

Our reviewers have identified these issues:

1. It appears the radiated measurements were taken without all of the ports being populated with the appropriate cables. Please supply a revised test report.
2. Please provide the calibration dates for the test equipment.

Best regards

Barry C. Quinlan  
Certification Manager  
Curtis-Straus TCB