



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

July 18, 2007

RE: Fleetwood Group Inc.

FCC ID: FBRWRS970X

I have a few comments on this Application.

1 The internal photos require that the shielding be removed from the transmitter. Please revise internal photos.

Response: There is no shield over the RF, this is the Ethernet connector box.

2 Please upload pseudo random hopping frequency list exhibit.

Response: Please refer to the revised operational description uploaded with this response.

Thank you,

A handwritten signature in black ink, appearing to read "Douglas E. Noble". The signature is fluid and cursive, with a large, stylized 'D' at the beginning.

Douglas E. Noble Examining  
Engineer

<mailto:dnoble@americanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.