

Report No.: 50092372 002

Type Designation: See main report






Picture 1- Inner view



Picture 2- Inner view

Rev. 1







Picture 3- Inner view




Picture 4- Power supply board
















Picture 6- Mainboard




Picture 7- Mainboard







Picture 8- Control board



Picture 9- Control board










Picture 11- Woofer and tweeter






Picture 12- Woofer and tweeter




Picture 13- Inner view







Picture 14- Inner view




Picture 15- Inner view











Picture 17- Internal air pipe






Picture 18- Transformer




Picture 19- Transformer






Picture 20- Transformer




Picture 21- Transformer






Picture 22- Transformer




Picture 23- Transformer






Picture 24- Transformer




Picture 25- Transformer





Picture 26- Transformer



Picture 27- Transformer

-- End of Attachment 1--