

External photo T1905 Tybble



External photo of LED driver:









Marking and position



Type label position

Type label:

120mm					
20mm	<table border="0"> <tr> <td style="text-align: center;">  <small>c</small> <small>US</small> Intertek 4002352 </td> <td> Type No. T1905 TYBBLE Made in China </td> <td> Conforms to:UL Std 1598 Certified to:CSA Std C22.2 No. 250.0 CAN ICES-005 (B) / NMB-005 (B) 120VAC 60Hz 0.19A </td> <td style="text-align: right;"> Sup. No. 22217  YYYWW </td> </tr> </table>	 <small>c</small> <small>US</small> Intertek 4002352	Type No. T1905 TYBBLE Made in China	Conforms to:UL Std 1598 Certified to:CSA Std C22.2 No. 250.0 CAN ICES-005 (B) / NMB-005 (B) 120VAC 60Hz 0.19A	Sup. No. 22217  YYYWW
 <small>c</small> <small>US</small> Intertek 4002352	Type No. T1905 TYBBLE Made in China	Conforms to:UL Std 1598 Certified to:CSA Std C22.2 No. 250.0 CAN ICES-005 (B) / NMB-005 (B) 120VAC 60Hz 0.19A	Sup. No. 22217  YYYWW		

120mm			
20mm	<table border="0"> <tr> <td> This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. </td> <td> FCC ID:FHO-T1905 DRY LOCATIONS ONLY POUR EMPLACEMENTS SECS SEULEMENT </td> </tr> </table>	This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.	FCC ID:FHO-T1905 DRY LOCATIONS ONLY POUR EMPLACEMENTS SECS SEULEMENT
This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.	FCC ID:FHO-T1905 DRY LOCATIONS ONLY POUR EMPLACEMENTS SECS SEULEMENT		