




Test Setup



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: AI1422V5
Test: 220210
Test to: 47CFR Parts 2, 90 and RSS-137
File: AI1422V5 TSup


SN: 21321992
PMN: AI1422 FCC ID: FIH1422PT90V5
IC: 1584A-1422R137V5
Date: March 9, 2022
Page 1 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: AI1422V5
Test: 220210
Test to: 47CFR Parts 2, 90 and RSS-137
File: AI1422V5 TSup


SN: 2132192
PMN: AI1422 FCC ID: FIH1422PT90V5
IC: 1584A-1422R137V5
Date: March 9, 2022
Page 2 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: AI1422V5
Test: 220210
Test to: 47CFR Parts 2, 90 and RSS-137
File: AI1422V5 TSup

SN: 21321992
PMN: AI1422 FCC ID: FIH1422PT90V5
IC: 1584A-1422R137V5
Date: March 9, 2022
Page 3 of 4



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: AI1422V5
Test: 220210
Test to: 47CFR Parts 2, 90 and RSS-137
File: AI1422V5 TSup

SN: 21321992
PMN: AI1422 FCC ID: FIH1422PT90V5
IC: 1584A-1422R137V5
Date: March 9, 2022
Page 4 of 4