


Internal photographs Transmitter PCB Primary Side shielding removed




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: E4V45
Test: 210519
Test to: 47CFR Parts 2, 90 and RSS-137
File: E4V45 IntPho

SN: ENG1, ENG2
FCC ID: FIHE4PT90V45
IC: 1584A-E4RSS137V45
Date: June 9, 2021
Page 1 of 4

Transmitter PCB Secondary Side




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: E4V45
Test: 210519
Test to: 47CFR Parts 2, 90 and RSS-137
File: E4V45 IntPho

SN: ENG1, ENG2
FCC ID: FIHE4PT90V45
IC: 1584A-E4RSS137V45
Date: June 9, 2021
Page 2 of 4

Inside enclosure (integral antenna side)



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: E4V45
Test: 210519
Test to: 47CFR Parts 2, 90 and RSS-137
File: E4V45 IntPho

SN: ENG1, ENG2
FCC ID: FIHE4PT90V45
IC: 1584A-E4RSS137V45
Date: June 9, 2021
Page 3 of 4

Inside enclosure (back side with power and communications interface board)



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: E4V45
Test: 210519
Test to: 47CFR Parts 2, 90 and RSS-137
File: E4V45 IntPho

SN: ENG1, ENG2
FCC ID: FIHE4PT90V45
IC: 1584A-E4RSS137V45
Date: June 9, 2021
Page 4 of 4