


Internal photographs Transmitter PCB Primary Side shielding removed




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: E4V5 PMN: E4 Reader
Test: 220119
Test to: 47CFR Parts 2, 90 and RSS-137
File: E4V5 IntPho

SN: ENG1
FCC ID: FIHE4PT90V5
IC: 1584A-E4RSS137V5
Date: February 18, 2022
Page 1 of 2

Transmitter PCB Secondary Side



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: E4V5 PMN: E4 Reader
Test: 220119
Test to: 47CFR Parts 2, 90 and RSS-137
File: E4V5 IntPho

SN: ENG1
FCC ID: FIHE4PT90V5
IC: 1584A-E4RSS137V5
Date: February 18, 2022
Page 2 of 2