


Test setup photographs



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Transcore  
Model: E4SPT90, HVIN: E4SPT90V1  
Test: 200915  
Test to: 47CFR Parts 2, 90 and RSS-137  
File: E4SPT90 TSup

SN's: Test unit 1, Test unit 2  
FCC ID: FIHE4SPT90V1  
IC: 1584A-E4SPT90V1  
Date: October 2, 2020  
Page 1 of 4



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Transcore  
Model: E4SPT90, HVIN: E4SPT90V1  
Test: 200915  
Test to: 47CFR Parts 2, 90 and RSS-137  
File: E4SPT90 TSup



SN's: Test unit 1, Test unit 2  
FCC ID: FIHE4SPT90V1  
IC: 1584A-E4SPT90V1  
Date: October 2, 2020  
Page 2 of 4



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Transcore  
Model: E4SPT90, HVIN: E4SPT90V1  
Test: 200915  
Test to: 47CFR Parts 2, 90 and RSS-137  
File: E4SPT90 TSup

SN's: Test unit 1, Test unit 2  
FCC ID: FIHE4SPT90V1  
IC: 1584A-E4SPT90V1  
Date: October 2, 2020  
Page 3 of 4



Rogers Labs, Inc.  
 4405 West 259<sup>th</sup> Terrace  
 Louisburg, KS 66053  
 Phone/Fax: (913) 837-3214  
 Revision 1

Transcore  
 Model: E4SPT90, HVIN: E4SPT90V1  
 Test: 200915  
 Test to: 47CFR Parts 2, 90 and RSS-137  
 File: E4SPT90 TSup

SN's: Test unit 1, Test unit 2  
 FCC ID: FIHE4SPT90V1  
 IC: 1584A-E4SPT90V1  
 Date: October 2, 2020  
 Page 4 of 4