


Internal photographs of MPI 6000.





ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

TRANSCORE AMTECH TECHNOLOGY CENTER
MODEL: MPI 6000
Test #: 051027 FCC ID#: FIH MPI6000
Test to: FCC Parts 2 and 90



Page 1 of 4

MPI6000 Int Photos.doc 11/8/2005



ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

TRANSCORE AMTECH TECHNOLOGY CENTER
MODEL: MPI 6000
Test #: 051027 FCC ID#: FIH MPI6000
Test to: FCC Parts 2 and 90




ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

TRANSCORE AMTECH TECHNOLOGY CENTER
MODEL: MPI 6000
Test #: 051027 FCC ID#: FIH MPI6000
Test to: FCC Parts 2 and 90

Page 3 of 4

MPI6000 Int Photos.doc 11/8/2005



Note there are no components located on printed circuit board sides not show in these photographs.

ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

TRANSCORE AMTECH TECHNOLOGY CENTER
MODEL: MPI 6000
Test #: 051027 FCC ID#: FIH MPI6000
Test to: FCC Parts 2 and 90

Page 4 of 4

MPI6000 Int Photos.doc 11/8/2005