



Single Port



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX5
Test: 220330
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX5 TSup


SN: 21104849 / 21230053
PMN: MPRX FCC ID: FIHMPRXPT90V5
IC: 1584A-MPRXR137V5
Date: May 16, 2022
Page 1 of 8



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX5
Test: 220330
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX5 TSup

SN: 21104849 / 21230053
PMN: MPRX FCC ID: FIHMPRXPT90V5
IC: 1584A-MPRXR137V5
Date: May 16, 2022
Page 2 of 8



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX5
Test: 220330
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX5 TSup

SN: 21104849 / 21230053
PMN: MPRX FCC ID: FIHMPRXPT90V5
IC: 1584A-MPRXR137V5
Date: May 16, 2022
Page 3 of 8




Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX5
Test: 220330
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX5 TSup

SN: 21104849 / 21230053
PMN: MPRX FCC ID: FIHMPRXPT90V5
IC: 1584A-MPRXR137V5
Date: May 16, 2022
Page 4 of 8



4 port



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX5
Test: 220330
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX5 TSup



SN: 21104849 / 21230053
PMN: MPRX FCC ID: FIHMPRXPT90V5
IC: 1584A-MPRXR137V5
Date: May 16, 2022
Page 5 of 8



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX5
Test: 220330
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX5 TSup

SN: 21104849 / 21230053
PMN: MPRX FCC ID: FIHMPRXPT90V5
IC: 1584A-MPRXR137V5
Date: May 16, 2022
Page 6 of 8



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX5
Test: 220330
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX5 TSup

SN: 21104849 / 21230053
PMN: MPRX FCC ID: FIHMPRXPT90V5
IC: 1584A-MPRXR137V5
Date: May 16, 2022
Page 7 of 8



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore
HVIN: MPRX5
Test: 220330
Test to: 47CFR Parts 2, 90 and RSS-137
File: MPRX5 TSup

SN: 21104849 / 21230053
PMN: MPRX FCC ID: FIHMPRXPT90V5
IC: 1584A-MPRXR137V5
Date: May 16, 2022
Page 8 of 8