

10.1 Tune-up Procedure

Factory alignment of the P-2000 and RT-2000 circuits require the use of equipment and proprietary test fixtures that are highly specialized and difficult to reproduce. The P-2000 and RT-2000 require factory alignment. Hence, the alignment procedures will not be offered in this report.

Both the output power level and frequency of the Internal Transceiver Modules (ITMs) may be fine adjusted by the customer, using appropriate test equipment and Motorola proprietary Customer Programming Software (CPS). This software must be purchased from Motorola and comes with an instruction guide on the CD-ROM.