

INTERTEK TESTING SERVICES

Report No.: HK10031355-1 Sample No.: 1/1 (Joystick)



Date: 8.APR.2010 13:49:35




Date: 8.APR.2010 13:50:31

Timming Plot – Pursuant to FCC Part 15 Section 15. 249 Requirement

INTERTEK TESTING SERVICES

Report No.: HK10031355-1 Sample No.: 1/1 (Joystick)



Date: 8.APR.2010 13:51:45

Timming Plot – Pursuant to FCC Part 15 Section 15. 249 Requirement