

DFS client device channel plan and software operational declaration

Date: 2016-05-20

We, Technicolor USA, Inc., declare that the device, FCC ID: G95TCA300 Model Name: TCA300COM, does not have "Ad Hoc on non-US frequencies" and/or "on DFS frequencies. Also, the client software and associated drivers will not initiate any transmission on DFS frequencies without initiation by a master. This includes restriction on transmissions for beacons and support for ad-hoc peer-to-peer modes.

Below is the channel / frequency plan for the device

	T	T	·			·					
CH	1	2	3	4	5	6	7	8	9	10	11
Frequency (MHz)	2412	2417	2422	2427	2432	2437	2442	2447	2452	2457	2462
Scan Type	Active	Active	Active	Active		Active	Active	Active		Active	Active

СН	36	38	40	44	46	48			
Frequency (MHz)	5180	5190	5200	5220	5230	5240		 	
Scan Type	Active	Active	Active	Active	Active	Active			


СН	52	54	56	60	62	64	
Frequency (MHz)	5260	5270	5280	5300	5310	5320	
Scan Type			Passive	Passive	Passive	Passive	

СН	100	102	104	108	110	112	116	118	120		-
Frequency (MHz)	5500	5510	5520	5540	5550	5560	5580	5590	5600		4
Scan Type	Passive	Passive	Passive	Passive	Passive	Passive	Passive	Passive	Passive	TAVA-4	
CH	124	126	128	132	134	136	140		J		1.,,
Frequency (MHz)	5620	5630	5640	5660	5670	5680	5700				
Scan Type	Passive	Passive	Passive	Passive	Passive	Passive	Passive				

СН	149	151	153	157	159	161	165	
Frequency (MHz)	5745	5755	5765	5785	5795	5805	5825	
Scan Type	Active							

Also, on DFS channels, the WLAN driver in the device operates under the control of an AP at all times, except when in ad-hoc mode, on US non-DFS channels. The device passively scans DFS frequencies until a master device is detected. The control of this functionality is not accessible to anyone under any conditions. Furthermore, the firmware is protected by special signature and CRC checksum. Signature and CRC checksum will be calculated and verified before firmware upgrade. Unauthorized modification to firmware will lead the failure of verification thus firmware upgrade is not allowed.

Sincerely yours,



Ervin Eilmann

Manager Technicolor Lab Services

Technicolor USA, Inc.

TEL: 317 587-4534 FAX: 317 587-9380

E-mail: ervin.eilmann@technicolor.com