

Dear Tim,

Please find the comments as below:

1. The tune-up procedure will be provided by Siemens.
2. The updated label location showed the location of GSM and BT label has been uploaded.
3. Uploaded
4. The updated user manual has been uploaded.
5. The updated user manual has been uploaded.
6. The updated user manual has been uploaded.
7. WLAN CF card is optional, and we will apply for PC II change to cover GSM+WLAN device.
8. Siemens power spec is just the general spec of GSM. The accurate targeted power will be shown in the tune-up procedure.
9. The updated external photo with the scanner has been uploaded.
10. The updated user manual has been uploaded.

BR
Daniel