


Report No. : FR710210-01

Appendix C. Set up Photograph

Conducted Emission

Mode 1



FRONT VIEW

REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C8
Report Issued Date : May 11, 2007
Report Version : Rev. 03



SIDE VIEW

Mode 2




FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C8

Report Issued Date : May 11, 2007 Report Version : Rev. 03





REAR VIEW






SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C8
Report Issued Date : May 11, 2007



Radiation Emission

Mode 1~6



FRONT VIEW


REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C8 Report Issued Date : May 11, 2007 Report Version

: Rev. 03

Mode 7~8



FRONT VIEW


REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C5 of C8
Report Issued Date : May 11, 2007



Mode 9~12 and 14~18



FRONT VIEW

REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C6 of C8
Report Issued Date : May 11, 2007

710210-01

Mode 13

FRONT VIEW



710210-01

REAR VIEW


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C7 of C8
Report Issued Date : May 11, 2007

Mode 19







SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C8 of C8
Report Issued Date : May 11, 2007
Report Version : Rev. 03