


Report No. : FR710210-01

# Appendix C. Set up Photograph

# Conducted Emission

Mode 1



FRONT VIEW

**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C8
Report Issued Date : May 11, 2007
Report Version : Rev. 03



SIDE VIEW

# Mode 2




FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C8

Report Issued Date : May 11, 2007 Report Version : Rev. 03





**REAR VIEW** 






SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C8
Report Issued Date : May 11, 2007



# **Radiation Emission**

#### Mode 1~6



**FRONT VIEW** 


**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C8 Report Issued Date : May 11, 2007 Report Version

: Rev. 03

#### Mode 7~8



FRONT VIEW


**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C5 of C8
Report Issued Date : May 11, 2007



### Mode 9~12 and 14~18



FRONT VIEW

**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C6 of C8
Report Issued Date : May 11, 2007

710210-01

#### Mode 13

FRONT VIEW



710210-01

REAR VIEW


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C7 of C8
Report Issued Date : May 11, 2007

#### Mode 19







SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C8 of C8
Report Issued Date : May 11, 2007
Report Version : Rev. 03