

To: "'tjohnson@americanTCB.com'" <tjohnson@americanTCB.com>
Subject: FCC ID: GSAK980MCW

FCC ID: GSAK980MCW

In reply to e-mail dated October 15, 2002

Dear Mr. Johnson,

Below are the answers to your questions.

1. Please find an external photograph of the back of the unit (External photo_back.pdf), submitted via "Add to existing application", External photos folder on October 22, 2002.
2. Please find the requested internal photographs (Internal photos_new.pdf), submitted via "Add to existing application", Internal photos folder on October 22, 2002.
3. A supervisory transmission lasts $1/3$ s (one burst of 6 messages). This information can be found in Appendix A of the Installation Instructions (A-2. Anti-Collision).
4. Visonic confirms that confidentiality is not requested.
5. Please find schematics of TX board (Tx module_schematics.pdf), submitted via "Add to existing application", Schematics folder on October 22, 2002.
6. Please find a 10 s plot in updated Operational description (Oper_descry_updated.pdf), submitted via "Add to existing application", Operational description folder on October 22, 2002.

With great respect,
Valeria