

**Barry C. Quinlan**

---

**From:** "Acme Testing" <acmetest@acmetesting.com>  
**To:** "Certification Manager" <certification@curtis-straus.com>  
**Sent:** Thursday, April 05, 2001 12:32 PM  
**Attach:** bandwidth plot.doc  
**Subject:** Re: FCC ID: GV364240

Thank you for your quick review of this application. I have responded to the following questions below.

Regards,

Desiree Patterson

----- Original Message -----

**From:** [Certification Manager](#)  
**To:** [Acme Testing](#)  
**Sent:** Wednesday, April 04, 2001 5:34 AM  
**Subject:** FCC ID: GV364240

We have identified the following issues during our review of the application:

1. Please confirm that a new battery was used for the testing.

[Per 15.231 \(e\), a new battery was used during testing.](#)

2. Please submit a bandwidth plot of the modulated signal so that we can confirm that the transmission remains within the band.

[A plot has been attached for your review.](#)

3. The label uses wording from 15.19(b) rather than 15.19(a). The product is subject to certification and not DoC. Please supply modified label details.

[The client has been notified of the incorrect label and will modify. Once the modification is complete, I will forward new label diagrams for your review.](#)

Best regards

Barry C. Quinlan  
Certification & Telecom Manager

-----  
Curtis-Straus LLC    Voice: 978.486.8880 x270  
527 Great Road     Fax: 978.486.8828  
Littleton, MA 01460 <http://www.curtis-straus.com>  
-----