
FCC TEST REPORT Report No.: F340709

1.1. Photographs of Conducted Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : GX9616PU
Page No. : 1 of 2
Issued Date : Apr. 19, 2003

FCC TEST REPORT Report No.: F340709

1.2. Photographs of Radiated Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



FRONT VIEW



REAR VIEW

SPORTON International Inc. TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : GX9616PU
Page No. : 2 of 2
Issued Date : Apr. 19, 2003