



CLIMAX TECHNOLOGY CO.,LTD.
大鵬科技股份有限公司

Date:2008/1/4

FEDERAL COMMUNICATIONS COMMISSION
Authorization and Evaluation Division
7435 Oaklamd Mills Road
Columbia, MD 21046
U.S.A.

Subject: Request to place FCCID GX9WTGS in audit mode / supersede Internal photo exhibit

To whom it may concern,

I would like to request the above referenced application to be placed into an audit mode in order to supersede the internal photos exhibits. It was determined by that the internal photos uploaded with the original application for Certification are wrong.

We provided 2 samples for test, and confirmed to test Lab. that both are identical. Due to an oversight, both of them are not identical. Test Lab. is considering the housing of EUT; it might destruct the product function during removing the housing. In order to protect the golden sample, we used one for test and the other for photograph. We have verified the sample tested is the product that is currently being manufactured and real shipment.

We look into our database and reconfirm all documents that had been uploaded to FCC, the test report, test set up photo, block diagram and schematics are correct and had double-confirmation.

Sincerely yours,

Signature : *George Lin*

Name/Title : George Lin / Hardware Engineer
Company : CLIMAX TECHNOLOGY CO., LTD.
Address : No.258, Sinhu 2nd Rd., Neihu District,
Taipei City 114, Taiwan (R.O.C.)
Tel. No. : 886-2-2794-0001
E-Mail : george@climax.com.tw