

Conducted Test Placement: (Photographs)



P/S: Because the space is not large enough for taking photograph of rear side. Please refer to the radiated testing set up.

Radiated Test Placement: (Photographs)





Report No.: S0715677, Wireless microphone receiver, FCC Class B

Test date: 04/20/98, Training Research Co., Ltd., TEL: 886-2-27881332, Fax: 886-2-27857408