

SEIKAKU TECHNICAL GROUP LIMITED

Offshore Chambers, P.O. Box 217 Apia, Samoa

Federal Communication Commission

Authorization and Evaluation Division

7435 Oakland Mills Road

Columbia, MD 21046

USA

RE: UP-82DR, UR-82DR, UP-81DR, UR-81DR, UP-8DR, AU-800R, MOD-800R

Gentlemen:

The scanner receiver equipment meets the requirements of FCC Rules, 15.121(a). Compliance is achieved through the following methods:

The scanner receiver in this equipment is incapable of tuning, or readily being altered, by the User to operate within the frequency bands allocated to the Domestic Public Cellular Telecommunications Service in Part 22. Blocking of the cellular frequencies is implemented in the firmware of the unit's main control central processing unit (CPU). Coverage of 824-829MHz and 869-894 MHz is completely blocked, since it is done in the microprocessor, and cannot be re-enabled by any user-accessible procedure, including diode, resistor, or jumper changes, nor by connection of any external device such as personal computer, nor installation of any "special" enabling semiconductor device.

The design is such that any attempts to modify the equipment to receive transmissions from the Cellular Radiotelephone Service likely will render the receiver inoperable.

Sincerely,



SEIKAKU Technical Group Limited

Henry Lee

Product Manager