

Helen Zhao

Subject: FW: FW: ADVANCE SECURITY INC., FCC ID: H5OTR18, Assessment NO.: AN06T5817, Notice#1

-----Original Message-----

From: wendy.wang

Sent: Tuesday, June 27, 2006 2:25 AM

To: Helen Zhao

Cc: lily.shu

Subject: Re:FW: ADVANCE SECURITY INC., FCC ID: H5OTR18, Assessment NO.: AN06T5817, Notice#1

Dear Helen:

Question #1: Please confirm the device is activated automatically or manually. It seems there is no button on the device, please explain why the test report shows "tested with button #1".
..>>The button #1 is on another transceiver device CX722(ID: H5OTR13) to trigger EUT's function.

Question #2: The user manual is too simple, it does not mention the basic operation. Please provide more detailed user manual.

..>>>Attached please find the new user manual.

Best Regards,
Wendy Wang

6/27/2006