

Askey Computer Corporation 10F, No. 119, Jiankang Rd., Zhonghe Dist., New Taipei City, 23585, Taiwan

Date: 2024-07-09

Re: Supersede request for FCC ID: H8NEAO2522P-2; Granted on 07/05/2024

To Whom It May Concern:

We regret to inform you that due to type the wrong Model No. on test reports, EUT photos and Operational Description, we have submitted the wrong Test reports, EUT photos and Operational Description exhibit to the filing.

To prevent misunderstanding to the public, we would like to request the FCC to supersede the exhibit described below:

Original	New	Change
Test Report (DSS)	Test Report (DSS)_rev	Modified the Model no. to
Test Report (DFS)_rev	Test Report (DFS)_rev 2	EAO2522P-2-FCC
Test Report (DTS-BT LE)	Test Report (DTS-BT LE)_rev	
Test Report (DTS-WLAN)_rev	Test Report (DTS-WLAN)_rev 2	
Test Report (NII)_rev 2	Test Report (NII)_rev 3	
RF Exposure Info (MPE)_rev 2	RF Exposure Info (MPE)_rev 3	
Operational Description_rev 2	Operational Description_rev 3	
External Photos	External Photos_rev	
Internal Photos_rev 2	Internal Photos_rev 3	

If you have any questions, feel free to contact us. Thank you.

Regards,

Jack Po, Manager Askey Computer Corp

Tel: 886 2 2228-7588 #18734

Fax: 886 2 3234-9340 E-mail: jackpo@askey.com