

**Helen Zhao**

---

**Subject:** FW: Re : RE: ASKEY COMPUTER CORP. FCC ID: H8NWLF3020 Assessment No. AN06T5623

-----Original Message-----

**From:** amanda.wu [mailto:amanda.wu@tw.ccsemc.com]**On Behalf Of** application

**Sent:** Tuesday, April 04, 2006 3:03 AM

**To:** Helen Zhao

**Subject:** Re : RE: ASKEY COMPUTER CORP. FCC ID: H8NWLF3020 Assessment No. AN06T5623

Dear Helen:

Please see my reply, thank you.

Best Regards

Amanda

-----Original Message-----

Sent: Monday, April 03, 2006 6:10 PM

Subject: ASKEY COMPUTER CORP. , FCC ID: H8NWLF3020, Assessment NO.:

AN06T5623, Notice#1

Question #1: The Class II permissive change letter indicates that antenna port has been relocated, from external photos, it seems RF path has been changed. Please redo Antenna port RF conducted test.

Ans: We had re-tested RF conducted test, please see the revised test report and appendix II.

Question #2: The original filing includes three antennas, one internal, two external PIFA and PCB antennas, this class II change filing indicates internal antenna has been removed, the EUT was tested with PIFA antenna only. Please confirm whether PCB antenna will be used or not.

Ans: By checking with customer, this device just use "Wanshih 3907-001100 / PIFA Antenna (External Antenna): 0dBi" only.

Best Regards,

Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

4/4/2006